

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 French Camp Slough	Left	1.76	10/04/2016 10/04/2016	Richard Willoughby

LM Start	0.00	Rating **	A	Issue No.	1
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0017_01_s _ 2013_1				
Comment Code					
Inspector Comment					
LMA has a copy of the manual on file.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	2
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0017_01_s _ 2013_2				
Comment Code					
Inspector Comment					
LMA has adequate flood fight supplies.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 French Camp Slough	Left	1.76	10/04/2016 10/04/2016	Richard Willoughby

No Photos

Photo 1 of 1 : FA_2016_RD0017_303_6_20161006_00016.jpg



Looking south typical view of waterward slope.

Photo 1 of 1 : FA_2016_RD0017_303_10_20161006_00017.jpg



Looking south at typical view of landward slope.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 French Camp Slough	Left	1.76	10/04/2016 10/04/2016	Richard Willoughby

LM Start	0.38	Rating **	C	Issue No.	12
LM End	0.38	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.913158°	37.913158°
				-121.296868°	-121.296868°
DWR ID	DWR_RD0017_01_s_2016_12				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/04/2016 10/04/2016	Richard Willoughby

LM Start	0.77	Rating **	C	Issue No.	77
LM End	0.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.906106°	37.906106°
				-121.323060°	-121.323060°
DWR ID	DWR_RD0017_02_s_2016_77				
Comment Code					
PR : Prunings					
Inspector Comment					
Landowner piling prunings at landward toe.					

No Photos

LM Start	1.08	Rating **	U	Issue No.	2	
LM End	1.08	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR Erosion Survey			37.902530°	37.902530°	
				-121.325690°	-121.325690°	
DWR ID						
Comment Code						
Inspector Comment						
07/25/2016: No significant change observed.						
06/24/2015: No significant change observed.						
06/19/2014: No significant change observed.						
08/13/2013: No significant change at this site.						
08/07/2012: The erosion is nearly vertical, and has developed upward						
to halfway of the levee slope. The protecting concrete blocks have been						
washed away. Animal activities are visible. [2016 Site						
ID:RD0017U02RM44.32]						

Photo 1 of 2 : SJR2016_RD0017U02RM44.32_1.jpg



Front view of the erosion site. Note the concrete blocks and vegetation at the site.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/04/2016 10/04/2016	Richard Willoughby

LM Start	1.08	Rating **	U	Issue No.	2 (cont)	
LM End	1.08	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR Erosion Survey			37.902530 °	37.902530 °	
				-121.325690 °	-121.325690 °	
DWR ID						
Comment Code						
Inspector Comment						
07/25/2016: No significant change observed. 06/24/2015: No significant change observed. 06/19/2014: No significant change observed. 08/13/2013: No significant change at this site. 08/07/2012: The erosion is nearly vertical, and has developed upward to halfway of the levee slope. The protecting concrete blocks have been washed away. Animal activities are visible. [2016 Site ID:RD0017U02RM44.32]						

Photo 2 of 2 : SJR2016_RD0017U02RM44.32_2.jpg



Close view of the erosion.

LM Start	1.29	Rating **	C	Issue No.	6
LM End	1.29	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.899510 °	37.899510 °
				-121.326030 °	-121.326030 °
DWR ID					
Comment Code					
Inspector Comment					
07/25/2016: No sign of erosion observed at the repaired site.					
06/24/2015: No significant change observed.					
06/19/2014: The erosion has been repaired. A minor erosion is still visible near the tree.					
08/13/2013: A mid-size tree is present immediately upstream of the erosion, which could block the view of the site. Some debris is visible.					
[2016 Site ID:RD0017U02RM44.52]					

No Photos

*** Location**
 LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable N : Not Inspected/Rated
 M : Minimally Acceptable C : Corrected
 U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
 Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/04/2016 10/04/2016	Richard Willoughby

LM Start	2.66	Rating **	C	Issue No.	8
LM End	2.66	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.881020 °	37.881020 °
				-121.332260 °	-121.332260 °
DWR ID					
Comment Code					
Inspector Comment					
07/25/2016: No sign of erosion was found at the repaired site. 06/24/2015: Erosion has been repaired. 06/19/2014: The erosion was probably caused by the irrigation pipe found at the site. [2016 Site ID:RD0017U02RM45.94]					

No Photos

LM Start	2.67	Rating **	C	Issue No.	10
LM End	2.69	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.880710 °	37.880710 °
				-121.332200 °	-121.332200 °
DWR ID					
Comment Code					
Inspector Comment					
07/25/2016: The construction work on the levee slope has been finished, and the erosion was repaired.					
06/24/2015: Levee has been cut at the mid slope and a temporary step has been made for unknown purpose. More erosion has been found at the site.					
6/19/2014: The erosion is in the river bank which has an estimated 10-ft wide berm. [2016 Site ID:RD0017U02RM45.95]					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/04/2016 10/04/2016	Richard Willoughby

LM Start	2.78	Rating **	C	Issue No.	82
LM End	2.79	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.879293 °	37.879293 °
				-121.332518 °	-121.332518 °
DWR ID					
Comment Code					
Inspector Comment					
07/25/2016: No sign of erosion observed at the repaired site.					
06/24/2015: No significant change observed.					
06/19/2014: The erosion has been repaired.					
08/13/2013: Found during boat survey. There is vegetation at the site.					
[2016 Site ID:RD0017U02RM46.03]					

No Photos

LM Start	2.82	Rating **	M	Issue No.	83
LM End	2.82	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.878660 °	37.878660 °
				-121.332400 °	-121.332400 °
DWR ID					
Comment Code					
Inspector Comment					
07/25/2016: No significant change observed.					
06/24/2015: No significant change observed.					
06/19/2014: A pocket erosion was found during the boat survey. [2016					
Site ID:RD0017U02RM46.1]					

Photo 1 of 2 : SJR2016_RD0017U02RM46.1_1.jpg



Front view of the erosion.

LM Start	2.82	Rating **	M	Issue No.	83 (cont)
LM End	2.82	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SJR2016_RD0017U02RM46.1_3.jpg



Close view of the erosion. The slope protection is poor.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/04/2016 10/04/2016	Richard Willoughby

LM Start	3.63	Rating **	C	Issue No.	84
LM End	3.63	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.868500 °	37.868500 °
				-121.327670 °	-121.327670 °
DWR ID					
Comment Code					
Inspector Comment					
07/25/2016: The erosion has been repaired. No new erosion found at the repaired site.					
06/24/2015: No significant change observed.					
06/19/2014: The erosion is near a large tree and probably has been caused by the irrigation pipe on the site. [2016 Site ID:RD0017U02RM46.89]					

No Photos

LM Start	3.73	Rating **	U	Issue No.	75
LM End	3.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.867233°	37.867233°
				-121.326712°	-121.326712°
DWR ID	DWR_RD0017_02_f_2016_75				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Large breaver holes on waterward berm					

Photo 1 of 2 : FA_2016_RD0017_304_75_20161006_00202.jpg



Looking east at beaver den on waterward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/04/2016 10/04/2016	Richard Willoughby

LM Start	5.52	Rating **	A/W	Issue No.	76
LM End	5.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.850118 °	37.850118 °
				-121.320188 °	-121.320188 °
DWR ID	DWR_RD0017_02_s_2012_76				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes has been backfilled, but should be monitored.					

No Photos

LM Start	6.74	Rating **	C	Issue No.	79
LM End	6.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.838810 °	37.838810 °
				-121.316600 °	-121.316600 °
DWR ID	DWR_RD0017_02_s_2015_79				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Removed cactus from waterward slope.					

No Photos

LM Start	7.25	Rating **	C	Issue No.	18
LM End	7.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.832612 °	37.832612 °
				-121.312093 °	-121.312093 °
DWR ID	DWR_RD0017_02_s_2013_18				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/04/2016 10/04/2016	Richard Willoughby

LM Start	7.42	Rating **	C	Issue No.	4
LM End	7.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.830350°	37.830350°
				-121.310880°	-121.310880°
DWR ID	DWR_RD0017_02_s_2012_4				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	7.58	Rating **	M	Issue No.	25
LM End	7.60	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.828095 °	37.827920 °
				-121.309945 °	-121.309847 °
DWR ID	DWR_RD0017_02_s_2012_25				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

Photo 1 of 1 : FA_2016_RD0017_304_25_20160929_00013.jpg



Elderberry blocking view of landside slope and toe.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/04/2016 10/04/2016	Richard Willoughby

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---